

Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 1: Wellhead Sign



Photo 2: Unused equipment removed



Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 3: Wellhead Sign



Photo 4: Unused equipment removed

Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 5: Wellhead Sign



Photo 6: Unused equipment removed

Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 7: Wellhead Sign



Photo 8: Weeds, stained soil removed

Location ID: 428602



Colorado Oil and Gas Conservation Commission
40.4631, -104.91949, 1441.8m, 350°
Aug 18, 2020 13:16:32

Photo 10: Unused equipment removed

Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 11: Wellhead Sign



Photo 12: Stained soil

Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 13: Wellhead Sign



Photo 14: Stained soil



Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 15: Unused equipment removed



Photo 16: Location of PA wellheads

Inspection Photos
Location Name: H-Y Pad & Tank Battery
Location ID: 428602



Photo 17: Tank Battery Removed