

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2020

Submitted Date:

08/18/2020

Document Number:

699801631

**FIELD INSPECTION FORM**

Loc ID 334463 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

22 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295035	WELL	PR	04/24/2013	GW	077-09550	NVEGA 23-324	PR
295036	WELL	PR	03/19/2008	GW	077-09551	NVEGA 23-234	PR
295037	WELL	PR	03/01/2011	GW	077-09552	NVEGA 23-231	PR
295750	WELL	PR	04/29/2008	GW	077-09637	NVEGA 23-144	PR
295751	WELL	PR	04/29/2008	GW	077-09636	NVEGA 26-211	PR
295752	WELL	PR	07/19/2008	GW	077-09635	NVEGA 26-111	PR
295753	WELL	PR	04/29/2008	GW	077-09634	NVEGA 26-311	PR
295754	WELL	PR	04/29/2008	GW	077-09633	NVEGA 23-141	PR
295755	WELL	PR	08/01/2019	GW	077-09632	NVEGA 23-241	PR
295756	WELL	PR	07/23/2013	GW	077-09631	NVEGA 23-341	PR
295757	WELL	PR	04/29/2008	GW	077-09630	NVEGA 23-244	PR
295758	WELL	PR	04/29/2008	GW	077-09629	NVEGA 23-344	PR
295759	WELL	PR	04/29/2008	GW	077-09628	NVEGA 23-331	PR
295760	WELL	PR	06/01/2012	GW	077-09627	NVEGA 23-334	PR

**General Comment:**

COGCC Inspection Report Summary

On Tuesday 8/18/20 at approximately 11:00 hours, I, Inspector Corey De Paolo,

Conducted an on-site inspection at LARAMIE ENERGY LLC NVega /4A,

Location #334463 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Sediment has migrated into the ditch that runs from the SW corner to the NW corner of location, along the base of the West cut slope. See photo #1739 and #1740 with a corrective action date of 9/2/20.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gallon	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	295035	Type:	WELL	API Number:	077-09550	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295036	Type:	WELL	API Number:	077-09551	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295037	Type:	WELL	API Number:	077-09552	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295750	Type:	WELL	API Number:	077-09637	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295751	Type:	WELL	API Number:	077-09636	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295752	Type:	WELL	API Number:	077-09635	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295753	Type:	WELL	API Number:	077-09634	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	295754	Type:	WELL	API Number:	077-09633	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID: 295755	Type: WELL	API Number: 077-09632	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 295756	Type: WELL	API Number: 077-09631	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 295757	Type: WELL	API Number: 077-09630	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 295758	Type: WELL	API Number: 077-09629	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 295759	Type: WELL	API Number: 077-09628	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 295760	Type: WELL	API Number: 077-09627	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Fail					
		Waddles	Pass			
Sediment Traps	Pass					
Berms	Pass					
		Gravel	Pass			
Waddles	Pass					
		Ditches	Pass			
Gravel	Pass					
		Culverts	Pass			
		Berms	Pass			
		Sediment Traps	Pass			
		Check Dams	Pass			

Comment: Sediment has migrated into the ditch that runs from the SW corner to the NW corner of location along the base of the West cut slope. See photo #1739 and #1740

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations. Repair BMP.

Date: 09/02/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801632	Photos for Insp. #699801631	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227275">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227275</a>