

Inspection Photos

Loc#314781

Operator: Chevron

Insp #: 692402442

Insp Date: 8/5/2020



Photo#1:
Overview of Location to Southeast

August 5, 2020



Photo#2:
Secondary containment on equipment has hog panel as cover;

Photo#3:
There is evidence of leaked fluids in containment.

August 5, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Wilson Creek Loc#314781



Photo#4:
Hog panel as cover.



Photo#5:
Equipment label.

August 5, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Wilson Creek Loc#314781



Photo#6:
Staining at Well head.



Photo#7:
Drip from process pipe.

August 5, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Wilson Creek Loc#314781



Photo#8:
Anchor marker down.



Photo#9:
Other open pipe/risers that should be capped/filled.

August 5, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Wilson Creek Loc#314781



Photo#10:
View along vegetated Fill Slope.



Photo#11:
View along Cut Slope.

August 5, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron Wilson Creek Loc#314781