



40.04879, -108.58432, 6804.3ft, 60°  
08/18/2020 05:24:09 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Calamity Ridge 14-15C      API: 05-103-10462**  
**Inspection: 700402970**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Pump jack.**

**Calamity Ridge 14-15C      API: 05-103-10462**  
**Inspection: 700402970**





40.04886, -108.58402, 6795.9ft, 205°  
08/18/2020 05:25:04 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Bull thistle weeds next to pump jack.**

**Calamity Ridge 14-15C**

**API: 05-103-10462**

**Inspection: 700402970**





40.0485, -108.58401, 6805.4ft, 133°  
08/18/2020 05:26:13 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tank & culvert.**

**Calamity Ridge 14-15C**

**API: 05-103-10462**

**Inspection: 700402970**





40 04888, -108 58375, 6805.5ft, 360°  
08/18/2020 05:26:54 PM




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Portable tanks.**

**Calamity Ridge 14-15C**

**API: 05-103-10462**

**Inspection: 700402970**







**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 7. Tank.**

**Calamity Ridge 14-15C**

**API: 05-103-10462**

**Inspection: 700402970**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 8. Tank stack.**

**Calamity Ridge 14-15C      API: 05-103-10462**  
**Inspection: 700402970**





40.04917, -108.58398, 6800.9ft, 92°  
08/18/2020 05:29:12 PM





40.04913, -108.584, 6805.3ft, 145°  
08/18/2020 05:30:07 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 10. Valve drilling fluid.**

**Calamity Ridge 14-15C**

**API: 05-103-10462**

**Inspection: 700402970**