


**Inspection Photos**  
**Location Name: Anne State 9-7**  
**Location ID: 329904**



**Photo 1 – Tank Battery. Produced Water Tanks missing NFPA Labels**



**Photo 2 – Wellhead**

**Inspection Photos**  
**Location Name: Anne State 9-7**  
**Location ID: 329904**



**Photo 3 – Gas Meter, No Current Calibration card**