

Final Reclamation Inspection

August 13, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336120

Inspection Document #: 697501901

Weld County, CO

NWSW Section 27 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BARCLAY #33-27
Location ID: 336120



08.13.2020 12:52

Photo 1. Photo taken from the well location, facing West. Photo illustrates the Operator has performed final reclamation activities, with the evidence of drill rows and straw crimped mulch.



Inspection Photos
Location Name: BARCLAY #33-27
Location ID: 336120



Photo 2. Photo taken from the well location, facing Northwest. Photo illustrates the other associated well located north of the PA location.

