

**Inspection Photos**  
**Location Name: Gordon 1**  
**Location ID: 326779**



**Photo 1 – Wellhead, Weeds, Unused Chemical Tank and Stand**



**Photo 2 – Tank Battery, Weeds**

**Inspection Photos**  
**Location Name: Gordon 1**  
**Location ID: 326779**



**Photo 3 – Gas Meter appears to not be updated on Calibration.**



**Photo 4 – Separator, Weeds**