

**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 1 – Tank Battery, Weeds**



**Photo 2 – Separator, Weeds**

**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 3 – Pumping Unit, Weeds**



**Photo 4 – Gas Meter, Weeds**

**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 5 – NW Deadman Anchors STILL NOT Marked**

**Photo 6 – Photo from Previous Inspection**

**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 7 – Burnt Debris STILL on Location**

**Photo 8 – Photo from Previous Inspection**

**Inspection Photos**  
**Location Name: State 26-2**  
**Location ID: 327091**



**Photo 9 – Trash STILL on Location**



**Photo 10 – Trash STILL on Location**