

# Inspection Photos

8/24/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334416

Mesa County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 1:** Aerial photograph taken from the southwestern areas of the pad, facing west. Photos 1-3 provide an overview of the production areas from north, northeast, to east.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 2:** See comments under photo 1. Photo also shows location of flowline spill.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 3:** See comments under photo 1..



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 4:** Photo shows the starting point for the disturbance area transect, facing east.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 5:** Photo shows the 50<sup>th</sup> point for the disturbance area transect, facing north.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 6:** Photo shows the 50<sup>th</sup> point for the disturbance area transect, facing south.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 7:** Photo shows the 50<sup>th</sup> point for the disturbance area transect.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 8:** Photo shows the end point for the disturbance area transect, facing west.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 9:** Photo shows the starting point for the reference area transect, facing south.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 10:** Photo shows the 50th point for the reference area transect, facing east.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 11:** Photo shows the 50th point for the reference area transect, facing west.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 12:** Photo shows the 50th point for the reference area transect





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334416



**Photo 13:** Photo shows the end point for the reference area transect, facing north

