

Inspection Photos
Location Name: Teets Perrin 1, 2, 3, 4 & 5 Battery
Location ID: 317716



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 1 TB sign

Photo 2 TB weeds overgrown on location

Inspection Photos

Location Name: Teets Perrin 1, 2, 3, 4 &5 Battery

Location ID: 317716



Photo 3 weeds overgrown in tank berm

Photo 4 weeds overgrown in berm and along outside

Inspection Photos

Location Name: Teets Perrin 1, 2, 3, 4 & 5 Battery

Location ID: 317716



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 5 weeds overgrown around Horizontal Heated Separator and flow lines.

Photo 6 weeds overgrown around Horizontal Heated Separator

Inspection Photos

Location Name: Teets Perrin 1, 2, 3, 4 & 5 Battery

Location ID: 317716



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 7 weeds overgrown around ECD.

Photo 8 weeds overgrown around flow lines

Inspection Photos

Location Name: Teets Perrin 1, 2, 3, 4 & 5 Battery

Location ID: 317716



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission


Photo 9 weeds overgrown around compressor house

Photo 10 compressor

Inspection Photos
Location Name: Teets Perrin 1, 2, 3, 4 & 5 Battery
Location ID: 317716



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 11 Gas Meter Run

Photo 12 Card in meter house indicates that calibration is not current