

Inspection Photos
Location Name: Teets Perrin 1
Location ID: 317716



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo 1 WH sign

Photo 2 weeds overgrown around WH

Inspection Photos
Location Name: Teets Perrin 1
Location ID: 317716



Photo 3 overgrown weeds around well

Photo 4 weeds overgrown around wellsite

Inspection Photos
Location Name: Teets Perrin 1
Location ID: 317716



Photo 5 overgrown weeds around transformer and meter box

Photo 6 weeds overgrown around wellsite