

Markus Production, INC, Jolly 41X-6
121-09826

Inspection #688308419

8/19/2020

PA/Equipment Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

MARKUS PRODUCTION, INC.
(303) 830-0998

JOLLY No. 41 X 6

NE NE SEC. 6-3S-55W

WASHINGTON COUNTY, CO

Colorado Oil and Gas Conservation Commission

39.82739, -103.57797, 4589.9ft, 150

08/19/2020 11:26:03 AM



Debric at
wellhead, location
is not reclaimed.

Colorado Oil and Gas Conservation Commission
39.74249, -103.59937, 174°
08/19/2020 11:15:51 AM



Wellhead location.

Colorado Oil and Gas Conservation Commission
39.8259, -103.57615, 4576.8ft, 124°
08/19/2020 11:16:09 AM




South pit.

Colorado Oil and Gas Conservation Commission
39.82778, -103.5777, 4583.3ft, 104°
08/19/2020 11:24:09 AM



South pit.

Colorado Oil and Gas Conservation Commission
39.82762, -103.57763, 4593.2ft, 28°
08/19/2020 11:25:07 AM



North pit.

Colorado Oil and Gas Conservation Commission
39.82761, -103.57788, 4606.3ft, 358°
08/19/2020 11:26:31 AM



Tank
battery
location.

Colorado Oil and Gas Conservation Commission

39.82767, -103.57772, 4586.6ft, 219°

08/19/2020 11:24:29 AM



Colorado Oil and Gas Conservation Commission

39.8275, -103.57787, 4596.5ft, 255°

08/19/2020 11:25:46 AM