

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /35SWNE

Location ID: 324471



Photo #1776 from entrance to location



Photo #1777 Multiple places with unused equipment.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /35SWNE

Location ID: 324471



Photo #1778 Multiple places with unused equipment.



Photo #1779 Multiple places with weeds on location.

Inspection Photos

Location Name: SG INTERESTS I LTD FEDERAL-611S90W /35SWNE

Location ID: 324471



Photo #1780 Multiple places with weeds on location.



Photo #1781 Flow line riser not LO/TO.