



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**WRD Unit 29-23**

**API: 05-103-10043**

**Inspection: 700403080**





40.11426, -108.18663, 5968.9ft, 285°  
08/25/2020 12:27:26 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Pump jack.**

**WRD Unit 29-23**

**API: 05-103-10043**

**Inspection: 700403080**





40.11426, -108.18663, 5968.9ft, 296°  
08/25/2020 12:29:00 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Separator & meter building.**

**WRD Unit 29-23**

**API: 05-103-10043**

**Inspection: 700403080**



40.11404, -108.18671, 5939.0ft, 341°  
08/25/2020 12:26:00 PM





40.11426, -108.18663, 5968.9ft, 49°  
08/25/2020 12:28:20 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 5. Chemical label.

WRD Unit 29-23

API: 05-103-10043

Inspection: 700403080







40.11068, -108.19064, 5955.6ft, 138°  
08/25/2020 12:23:41 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 7. Thistle on edge of road.**

**WRD Unit 29-23**

**API: 05-103-10043**

**Inspection: 700403080**