

BP L48 San Juan



V2 Compliance Follow Up Form

18152332771

Reference Number:	20200820-18152332771
Form Name:	V2 Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com) colen@horizonenvservices.com
Submission Date:	Aug 20, 2020 4:17:25 PM MDT
Location:	91 S Skylane Dr, Durango, CO 81303, USA Aug 20, 2020 4:20:03 PM MDT [View Map]

INFORMATION

Section 1

Name	colen@horizonenvservices.com
Date	Aug 19, 2020
Well Name	RICHARDSON GAS UNIT 01-25 1
API Number	50670650700
Select State	Colorado
Work type	BP call out
Action Complete	Clean Up Weed Debris
Photo of first corrective action completed	



Completed work description Corrective Action 1 location sign
Photo of second corrective action completed



Completed work description of corrective action 2 equipment clear

Photo of third corrective action completed



Completed work description of corrective action 3 equipment clear
Photo of fourth corrective action completed



Completed work description

removed weed debris on pad

Completed work description of corrective action 4

removed weed debris on pad

Completed work description

removed weed debris

Summary of all work completed

previous treatment dates 7/21/16, 7/13/17, 7/10/18, 6/25/19