



**Reference Number:** 20200820-18152336266  
**Form Name:** V2 Compliance Follow Up Form  
**Submitter Name:** Cole Nichols (colen@horizonenvservices.com) | colen@horizonenvservices.com  
**Submission Date:** Aug 20, 2020 4:56:02 PM MDT  
**Location:** 91 S Skylane Dr, Durango, CO 81303, USA  
 Aug 20, 2020 4:55:43 PM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

**Name** colen@horizonenvservices.com  
**Date** Aug 19, 2020  
**Well Name** CARLSON GAS UNIT 32-01 1  
**API Number** 50670663100  
**Select State** Colorado  
**Work type** COGCC Inspection AR  
**Action Complete** Other

#### Photo of first corrective action completed



**Completed work description Corrective Action 1**

location sign

**Photo of second corrective action completed**



**Completed work description of corrective action 2**

treated Russian knapweed populations

**Photo of third corrective action completed**



**Completed work description of corrective action 3**

treated noxious weeds

**Photo of fourth corrective action completed**



**Completed work description**

treated Russian knapweed populations

**Completed work description of corrective action 4**

treated noxious weeds

**Completed work description**

treated noxious weeds

**Summary of all work completed**

previous treatment dates 6/29/16, 7/28/17, 5/30/18, 4/8/19, 6/12/20