

BP L48 San Juan



V2 Compliance Follow Up Form

18152335695

Reference Number:

20200820-18152335695

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Submission Date:

Aug 20, 2020 5:02:11 PM MDT

Location:

91 S Skylane Dr, Durango, CO 81303, USA
Aug 20, 2020 5:01:41 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Aug 19, 2020

Well Name

TAICHERT GAS UNIT 32-02 1

API Number

50670664100

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Other

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed**Completed work description of corrective
action 2**

treated Russian thistle

Photo of third corrective action completed**Completed work description of corrective
action 3**

treated Canada thistle

Photo of fourth corrective action completed



Completed work description

treated Russian knapweed populations

Completed work description of corrective action 4

treated noxious weeds

Completed work description

treated noxious weeds

Summary of all work completed

previous treatment dates 7/20/16, 7/28/17, 5/30/18, 4/8/19, 5/13/20