

BP L48 San Juan



V2 Compliance Follow Up Form

18152334808

Reference Number:

20200820-18152334808

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Submission Date:

Aug 20, 2020 5:08:56 PM MDT

Location:

91 S Skylane Dr, Durango, CO 81303, USA
Aug 20, 2020 5:08:44 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Aug 18, 2020

Well Name

HOTT GAS UNIT 29-02 2

API Number

50670690500

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Other

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

treated Russian knapweed populations

Photo of third corrective action completed



**Completed work description of corrective
action 3**

treated Russian knapweed populations

**Completed work description of corrective
action 4**

treated Russian knapweed populations

Completed work description

treated Russian knapweed populations

Summary of all work completedprevious treatment dates 6/16/16, 7/28/17,
5/31/18, 4/9/19, 7/15/20