

Inspection Photos

API: 05-071-07968

Operator: PRESCO INC

Inspection Date: 8/25/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/25/2020

Inspection Photos



Photo 1. Facing east along the pre-existing access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/25/2020

Inspection Photos



Photo 2. There was rock utilized along the side of the road which has crated additional disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/25/2020

Inspection Photos



Photo 3. Facing southeast along the pre-existing access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/25/2020

Inspection Photos



Photo 4. There was rock utilized along the side of the road which has crated additional disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/25/2020

Inspection Photos



Photo 5. Facing northeast toward the location. Vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/25/2020