

Inspection Photos
Location Name: Five Rivers K 10-30 D Pad
Location ID: 420414



Lease road from county road to well pad



Well pad

Inspection Photos
Location Name: Five Rivers K 10-30 D Pad
Location ID: 420414



Colorado Oil And Gas Conservation Commission
40.33384, -104.77126, 1431.0m
08/27/2020 10:43:38 AM

Lease road from tank battery to well pad



Colorado Oil And Gas Conservation Commission
40.33367, -104.77158, 1392.0m
08/27/2020 10:40:30 AM

Production facility

Inspection Photos
Location Name: Five Rivers K 10-30 D Pad
Location ID: 420414



Unused meter run



Unused separators

Inspection Photos
Location Name: Five Rivers K 10-30 D Pad
Location ID: 420414



Unused ECD's



Unused crude oil tanks

Inspection Photos
Location Name: Five Rivers K 10-30 D Pad
Location ID: 420414



Unused produced water vaults



Battery sign

Inspection Photos
Location Name: Five Rivers K 10-30 D Pad
Location ID: 420414



Battery sign and ECD scrubbers



Battery sign

Inspection Photos
Location Name: Five Rivers K 10-30 D Pad
Location ID: 420414



Battery sign