

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/27/2020

Submitted Date:

08/27/2020

Document Number:

700701429**FIELD INSPECTION FORM**
 Loc ID 416722 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416837	WELL	DG	10/08/2019	LO	045-19372	McLin B2	DG
416839	WELL	PR	07/02/2014	GW	045-19373	McLin B19	PR
416840	WELL	DG	10/08/2019	LO	045-19374	McLin B14	DG
416842	WELL	PR	10/29/2012	GW	045-19375	McLin B9	PR
416843	WELL	PR	03/30/2015	LO	045-19376	McLin B6	PR
416844	WELL	PR	01/17/2012	GW	045-19377	McLin B3	PR
416845	WELL	DG	10/08/2019	LO	045-19378	McLin B1	DG
416848	WELL	PR	01/17/2012	GW	045-19379	McLin B7	PR
416849	WELL	PR	01/24/2014	GW	045-19380	McLin B11	PR
416851	WELL	PR	01/19/2014	GW	045-19381	McLin B17	PR
416852	WELL	PR	01/19/2014	GW	045-19382	McLin B15	PR
416855	WELL	PR	01/19/2014	GW	045-19383	McLin B20	PR
416856	WELL	PR	01/19/2014	GW	045-19384	McLin B16	PR
416858	WELL	DG	10/08/2019	LO	045-19385	McLin B12	DG
416859	WELL	DG	10/08/2019	LO	045-19386	McLin B10	DG
416860	WELL	PR	07/02/2014	GW	045-19387	McLin B8	PR
416861	WELL	DG	10/08/2019	LO	045-19388	McLin B13	DG
416862	WELL	PR	10/29/2012	GW	045-19389	McLin B5	PR
416863	WELL	PR	03/30/2015	LO	045-19390	McLin B4	PR
416864	WELL	PR	07/02/2014	GW	045-19391	McLin B18	PR
434060	WELL	PR	06/15/2016	LO	045-22156	McLin B21	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 8/27/20 at approximately 1030, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa McClin B, at Location # 416722 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. All C/A(s) from previous inspection document # 700701299 have been completed.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	chemical tank at well heads		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,
Comment:	one tank is not heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,
Comment:	shared containment with condensate tanks				

Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type	Ignitor/Combustor				
Comment:					
Corrective Action:				Date:	

Inspected Facilities				
Facility ID:	416837	Type:	WELL	API Number: 045-19372 Status: DG Insp. Status: DG
Facility ID:	416839	Type:	WELL	API Number: 045-19373 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	416840	Type:	WELL	API Number: 045-19374 Status: DG Insp. Status: DG
Facility ID:	416842	Type:	WELL	API Number: 045-19375 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	416843	Type:	WELL	API Number: 045-19376 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	416844	Type:	WELL	API Number: 045-19377 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	416845	Type:	WELL	API Number: 045-19378 Status: DG Insp. Status: DG
Facility ID:	416848	Type:	WELL	API Number: 045-19379 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	416849	Type:	WELL	API Number: 045-19380 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	416851	Type:	WELL	API Number: 045-19381 Status: PR Insp. Status: PR

<u>Producing Well</u>				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 416852 Type: WELL API Number: 045-19382 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 416855 Type: WELL API Number: 045-19383 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 416856 Type: WELL API Number: 045-19384 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 416858 Type: WELL API Number: 045-19385 Status: DG Insp. Status: DG				
Facility ID: 416859 Type: WELL API Number: 045-19386 Status: DG Insp. Status: DG				
Facility ID: 416860 Type: WELL API Number: 045-19387 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 416861 Type: WELL API Number: 045-19388 Status: DG Insp. Status: DG				
Facility ID: 416862 Type: WELL API Number: 045-19389 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	producing			
Corrective Action:			Date:	
Facility ID: 416863 Type: WELL API Number: 045-19390 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	producing			
Corrective Action:			Date:	

Inspector Name: Ramsey, Scott

Facility ID:	416864	Type:	WELL	API Number:	045-19391	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	434060	Type:	WELL	API Number:	045-22156	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Ditches				
Berms		Culverts				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701434	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5234131