

Inspection Photos
Location Name: Wildhorse 16 SWD
Location ID: 159595



Photo 1 – Facility Sign at Entrance




Photo 2 - Produced Water Signage

Inspection Photos
Location Name: Wildhorse 16 SWD
Location ID: 159595



Photo 3 – Produced Water Signage



Photo 4 – Weeds at Berms

Inspection Photos
Location Name: Wildhorse 16 SWD
Location ID: 159595



Photo 5 – Weeds at Berms



Photo 6 - Produced Water Signage

Inspection Photos
Location Name: Wildhorse 16 SWD
Location ID: 159595



Photo 7 – Crude Oil Tanks



Photo 8 - Produced Water Signage

