

Inspection Photos
Location Name: Our Diane #32-27
Location ID: 318149



Photo 1 WH Dead weeds on location and around location.



Photo 2 Improper fluid storage 55gal drum. Stained soil around 55gal drum.

Inspection Photos
Location Name: Our Diane #32-27
Location ID: 318149



Photo 3 Stained soil around PU motor and exhaust pipe



Photo 4 Stained soil around PU motor. Mechanical issue: stained soil appears to be coming from leaking PU motor.