

Inspection Photos

Loc#313011

Operator: Bayless

Insp#: 692402463

Insp Date: 8/25/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to West.

August 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Bayless Zimmerman/Chamberlin Loc#313011



Photo#2:
Kochia growth.



Photo#3:
Kochia growth.

August 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Bayless Zimmerman/Chamberlin Loc#313011



Photo#4:
Views of failed area of Interim.



Photo#5:
Views of failed area of Interim.

August 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Bayless Zimmerman/Chamberlin Loc#313011



Photo#6:
Sediment migration & developing erosion at West side of Location.

Photo#7:

August 25, 2020



Photo#8:
Sediment migration & developing erosion at West side of Location.

August 25, 2020