

# Inspection Photos

API: 071-06128

Operator: TIMBER CREEK OPERATING

Inspection Date: 8/27/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 1.** It appears noxious weeds were controlled along the road. Some of the grass vegetation appears to be browning as well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 2.** There is a plugged culvert along the main road (red arrow) causing stormwater to flow down the road. Lat/Long:37.09178,-104.93688.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 3.** There is sediment accumulation at the bottom of the road which appears to be coming uphill from the access road or pipeline area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 4.** BMP's are needed along the side of the road to dissipate stormwater flow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 5.** Stormwater is flowing down the road which is causing erosion and degradation of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 6.** The culvert is plugged up along the road causing stormwater to flow down the road as shown in the previous photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 7.** Facing southwest along the access road. There is erosion occurring down the road. The blue plastic debris from pipe should be picked up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020

## Inspection Photos



**Photo 8.** The water in the pit is approaching 2 ft. freeboard.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 8/27/2020