

Pit Status Evaluation Form

Pit Overview:

Pit Name: CHAMPLIN 86 "G"	Facility ID: 118689
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: CHAMPLIN 86 G #1 (API 123-12406 Facility ID 244611; Loc ID 335562)	

County: WELD

Township: 1N **Range:** 68W **Section:** 17 **QQ:** CSW

Original Latitude/ Longitude: 40.047247 / -104.884052

Updated Latitude/ Longitude: /

Basis for Location Change:

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 696920 | Date: 12/16/1986 |
| | Doc #: 32827 | Date: 3/20/1996 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input checked="" type="checkbox"/> | Other: 60828 - 1993 Certification of clearance notes water goes to a commercial pit | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location.

Pit Status Review Summary:

Based on records review and aerial imagery there is no evidence that there was a pit on location. Inspections document a produced water tank on location. Pit status has been changed to closed.

