

Inspection Photos
Location Name: Kerith Rothrock #1
Location ID: 317501



Photo 1 – Tank Battery Sign




Photo 2 – Pumping Unit

Inspection Photos
Location Name: Kerith Rothrock #1
Location ID: 317501



Photo 3 – Weeds at Wellhead




Photo 4 – Stained Soil at Wellhead

Inspection Photos
Location Name: Kerith Rothrock #1
Location ID: 317501



Photo 5 – Unused Tubing and Rod Strings



Photo 6 – Wellhead Sign

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 7 –Heater Treater Weeds



Photo 8 – Skim Tank Missing Labels – Content, Capacity and NFPA

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 9 – Weeds at Tank Battery



Photo 10 – Unmarked Risers at Tank. Weeds

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 11 – Weeds in Pit Area



Photo 12 – Weeds in Pit Area