

Inspection Photos
Location Name: Dwinell 2
Location ID: 324590



Photo 1. Wellhead sign knocked over. Door to housing stuck shut.