

BP L48 San Juan



V2 Compliance Follow Up Form

18153221448

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200828-18153221448

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 21, 2020 1:28:07 PM MDT

172 Rattle Snake Dr, Ignacio, CO 81137, USA

Aug 21, 2020 1:25:00 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 17, 2020
Well Name	REA, RONALD GAS UNIT 2
Location Name (Other)	REA , RONALD GAS UNIT 4
API Number	50670832900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Land Owner Debris Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Fixed erosion

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Fixed erosion

Photo of fourth corrective action completed



Completed work description

Installed rock run down

Completed work description of corrective action 4

Installed new well equipment signs

Additional photos



Additional photos



Additional photos



Summary of all work completed

Compliance, installed rock run down , fixed erosion picked up trash, cleaned up trash