

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 1 – Pumping Unit



Photo 2 – Heater Treater

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 3 – Tank Battery



Photo 4 – Wellhead Sign

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 5 – No current date of Calibration on Card

Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 7 – Stained Soil at Gas Engine



Photo 8 – Stained Soil at North Loadline

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 9 – Stained Soil at Wellhead



Photo 10 – Weeds in Pit Area

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 9 – Weeds in Pit Area



Photo 10 – Weeds in Pit Area

Inspection Photos
Location Name: Craig #2
Location ID: 327437



Photo 11 – Weeds in Pit Area