

## Inspection Photos

Location Name: HOWARD USX A-66N64W /9NWSE

Location #: 306349



**Photo #1**

Howard USX A 9-10 (05-123-24495) Wellsite

**Producing | PR**

**Weeds**



**Photo #2**

Howard USX A 09-14D, 09-15D, 09-23, 9-10, 9-11

Battery site

**Active**

*Formerly served:*

*Howard USX A09-09D, A 9-16*

*Plugged & Abandoned | PA*