

Inspection Photos
Location Name: Sullivan, M C SWD 1
Location ID: 315800



Photo 1. Overview of location taken facing north.

Inspection Photos
Location Name: Sullivan, M C SWD 1
Location ID: 315800



Photo 2. Wellhead sign knocked over.



Photo 3. Photo of wellhead inside housing.