

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/01/2020

Submitted Date:

09/01/2020

Document Number:

699102319

**FIELD INSPECTION FORM**Loc ID 419653 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419656	WELL	PR	10/01/2018	OW	123-32301	AMEN PC D 06-18D	SI
419658	WELL	PR	11/01/2018	GW	123-32302	HOFF PC D 06-21	SI
419662	WELL	PR	11/01/2018	GW	123-32304	SHELTON PC D 06-32D	SI
419693	WELL	PR	11/01/2018	GW	123-32322	SMITH PC D 06-20D	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:	Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel x4		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	OTHER	BV CONCRETE		,	
Comment:	Shares berms w/ production tanks.					
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)	60 BBL	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	300 BBLS	STEEL AST		40.254800,-104.593600	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 419656 Type: WELL API Number: 123-32301 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, LO/TO.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 419658 Type: WELL API Number: 123-32302 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, LO/TO.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 419662 Type: WELL API Number: 123-32304 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, LO/TO.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 419693 Type: WELL API Number: 123-32322 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI, LO/TO.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 9/1/20 at approximately 0846hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Hoff PC D 06-21 of Noble Energy at Location ID: 419653 in Weld County, Colorado.</p> <p>While there, I observed 4 wells that are SI, LO/TO.</p> <p>No violation of the COGCC rules were observed at the time of inspection.</p> <p>This is a summary of inspection report.</p>	burnsa	09/01/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699102320	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238112">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5238112</a>