

Inspection Photos

API: 071-09637

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/2/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09637 | Date: 9/2/2020

Inspection Photos



Photo 1. Facing east along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09637 | Date: 9/2/2020

Inspection Photos



Photo 2. Facing east further along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09637 | Date: 9/2/2020

Inspection Photos



Photo 3. Facing northwest toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09637 | Date: 9/2/2020

Inspection Photos



Photo 4. Facing southwest toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09637 | Date: 9/2/2020

Inspection Photos



Photo 5. Facing south at the location. The road continues past the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09637 | Date: 9/2/2020