

Inspection Photos

API# 081-07592

Operator: GRMR

Insp#: 692402490

Insp Date: 8/27/2020



Photo#1:
View of Location to Southeast.

August 27, 2020



Photo#2:
View of Location to Northwest.

August 27, 2020



Photo#3:

Heavy growth of Curly cup gumweed at Southwest end of site; insert is catchment basin. at terminating corner.

August 27, 2020



Photo#4:
View along West edge of site to South.

August 27, 2020