

Inspection Photos
Location Name: Elk Springs Unit 4
Location ID: 311770



Photo 1. Overview of location taken facing east.

Inspection Photos
Location Name: Elk Springs Unit 4
Location ID: 311770



Photo 2. Active injection at time of inspection.



Photo 3. Equipment stored on location.

