

Inspection Photos

9/04/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334067

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334067



Photo 1: Photo taken from the west end of the Location facing south. Photos 1-3 provide an overview of the Location from south, southwest, to northwest.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334067



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334067



Photo 3: See comments under photo 3

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334067



Photo 4: Photo taken from the wells, facing northeast. Photo shows the 3 active wells remaining on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334067



Photo 5: Photo shows what appears to be pressure gauges and tubing associated with the PA well. Equipment is unused and requires removal.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334067



Photo 6: Continued from photo 5.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334067



Photo 7: Photo taken from the northwest end of the Location, facing north. Photo shows erosion degradation due to stormwater runoff from the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334067



Photo 8: Continued from photo 7. Photo shows erosion degradation due to stormwater runoff from the Location.