

Inspection Photos

9/04/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334151

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334151



20200904

Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-3 provide an overview of the Location from east, south, to west.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334151



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334151



Photo 3: See comments under photo 3



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334151



Photo 4: Photo shows only well remaining on the Location. Well status TA. All other production equipment has been remove from the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334151



Photo 5: Photo taken from the north end of the Location, facing south. Photo show example of areas where subsidence concerns are evident on the Location.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334151



Photo 6: Photo taken from the west end of the Location, facing south. Photo show example of areas where subsidence concerns are evident on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources