

Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 1. Overview of location taken facing south.

Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 2. Stained soil at separator.



Photo 3. Stained soil at separator.



Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 4. Stained soil at pump jack motor.



Photo 5. Pit.

