

Inspection Photos
Location Name: State 41-14-1
Location ID: 424085



Photo 1. Overview of location taken facing northeast. Site degradation continuing.



Photo 2. Tubing stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources