

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 1. Overview of location taken facing southeast.



Photo 2. Overview of location taken facing southeast.



Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 3. Tubing stored on location.



Photo 4. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources