

**Inspection Photos**  
**Location Name: Wickstrom 6 CTB**  
**Location ID: 435380**



**Photo 1 – Tank Battery**



**Photo 2 – Tank Battery Sign**



**Inspection Photos**  
**Location Name: Wickstrom 6 CTB**  
**Location ID: 435380**



Colorado Oil and Gas Conservation Commission  
40.61113, -104.02599, 4906.7ft, 113°  
09/02/2020 15:11:22

**Photo 3 – Tank Battery Sign**



Colorado Oil and Gas Conservation Commission  
40.61107, -104.02582, 4903.2ft, 324°  
09/02/2020 15:11:38

**Photo 4 – Day Tank – missing Wildlife Netting**





**Inspection Photos**  
**Location Name: Wickstrom 6 CTB**  
**Location ID: 435380**



**Photo 5 – Unmarked Riser South of Heater Treaters**



**Photo 6 – Unmarked Riser South of Pit**

**Inspection Photos**  
**Location Name: Wickstrom 6 CTB**  
**Location ID: 435380**



**Photo 7 – Stained Soil at North Loadlines**



**Photo 8 – Holes in Netting**





**Inspection Photos**  
**Location Name: Wickstrom 6 CTB**  
**Location ID: 435380**



**Photo 9 – Holes in Netting**



**Photo 10 – Holes in Netting**





**Inspection Photos**  
**Location Name: Wickstrom 6 CTB**  
**Location ID: 435380**



**Photo 11 – Holes in Netting**



**Photo 12 – Holes in Netting**