

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /11NESW

Location ID: 312702



Network: Sep 9, 2020 at 12:01:19 PM MDT
Local: Sep 9, 2020 at 12:01:19 PM MDT



Network: Sep 9, 2020 at 12:01:55 PM MDT
Local: Sep 9, 2020 at 12:01:55 PM MDT

Photo #1857 from entrance to location

Photo #1858 Multiple places with debris on location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP-68S96W /11NESW

Location ID: 312702



Photo #1859 Multiple places with debris on location.