

Inspection Photos
Location Name: Bashor 18-1
Location ID: 323023



Photo 1 – Tank Battery



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Bashor 18-1
Location ID: 323023



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Stained Soil at Wellhead

Inspection Photos
Location Name: Bashor 18-1
Location ID: 323023



Photo 5 – Stained Soil at Heater Treater




Photo 6 – Unmarked Risers on the Northside of Crude Oil Tanks