

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Nielson #3 location photo.



Unused bucket and container with oily contents.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Container with oily contents.



Nielson #3 tank battery. Photo taken from near well head.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Nielson #3 tank battery. Weeds present within secondary containment berm.



Stained soil beneath load out valve on north AST.