



99999999

ADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT☐ NOTICE OF UNSATISFACTORY INSPECTION1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05- 075 - 8346

LEASE NAME: *Svedlund 1*LOCATION: *SWNW 4-9N-53*OPERATOR: *Western*DATE: *1-24-96*INSPECTOR: *Ed Binkley*Insp. Type: *Pr*Insp. Status: *Pr*

PA: Y

N

Pass/Fail: P *(F)*

Viol.: Y

(N)

NOV: Y

(N)

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	<i>Improve dikes & berms when</i>	
Spills (Oil/Water) (Rule 908)	<i>ground is workable.</i>	
Bradenhead (Rule 207)	<i>Cultivate oily soil around</i>	
Drilling Well/Workover (Rule 315)	<i>well and battery.</i>	
Surface Rehabilitation (Rule 317)		
Miscellaneous		



00269820

CORRECTIVE ACTION REQUIRED: *Post directional sign at county road access to this lease.*Date Corrective Action Required By: *3-30-96*

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.