

Inspection Photos
Location Name: Marick 15-29
Location ID: 310384



Photo 1 – Pumping Unit, Wellhead. Unused Chemical Tank, Pump, Stand and Containment. Unused Wellhead Parts



Photo 2 – Unused Tubing, Wellhead Parts

Inspection Photos
Location Name: Marick 15-29
Location ID: 310384



Photo 3 – Wellhead Sign, Unused Wellhead Parts



Photo 4 – Unused Secondary Containment

