

**Inspection Photos**  
**Location Name: Marick 9-29**  
**Location ID: 310385**




**Photo 1 – Pumping Unit, Wellhead. Unused Chemical Tank, Pump, Stand and Containment. Unused Wellhead Parts**



**Photo 2 – Unused Tubing, Wellhead Parts**

**Inspection Photos**  
**Location Name: Marick 15-29**  
**Location ID: 310384**



Colorado Oil and Gas Conservation Commission  
40.891, -104.22247, 5102 ft, 211°  
09/09/2020 13:55:52

**Photo 3 – Wellhead Sign**