

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Variance Tag. See attached photo.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Non-Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Appears to be plumbed to surface.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pig Station	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.247000,-104.552000
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		
Comment:	Shares containment with crude oil tank.				Date:
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 297393 Type: WELL API Number: 123-27115 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 9/11/20 at approximately 0930hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Front Range D 9-28 of Noble Energy at Location ID: 310851 in Weld County, Colorado. While there, I observed a well that is SI, with the yellow "LTSI" variance tag. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p>	burnsa	09/11/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102368	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5244951