



WELL SITE INSPECTION FORM

Well Name EATON #1
Operator MC MURRAY OIL CO.
Location SENE5-9N-53W
Field WINDSONG

API Number 05-075-08324
Permit # 72-0138
County LOGAN
Inspector R. Van Sickle



AL/PA/DA Inspection Results:

Well Status:

Pass(Y) Fail(N) X Date 4-18-90 FN FD WO PR SI

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
Consistent with APD casing Program? YES NO Returns
Rig BOP'S Contact

Date of Inspection Before/During/After Completion

Prod. Csg. Set? Completion Rig/Activity
Drilling Pits: Closed Open Wellhead Installed Y N
Tank ID: Yes No N/A Skim Tank/Pit: Prod. Tanks: () BBLs
Equipment Meter Run: Yes No
Bradenhead Press: Fluid: No Yes Type Well Cat.

AL/PA/DA Inspection

Date Plugged: 7-12-88 Date Permit Expired:
Hole Plugged: Yes X No Pits Backfilled: Yes X No
Material Buried: Yes X No N/A Site Clean: Yes No X
Bond Release OK: Yes No X Fed Hole Marker: Yes No X

Date of Safety/Status Inspection

Comments: REMOVE WS ANCHORS & FILL IN THE HOLE @
WH.

Violations: Yes No X Notice Sent: Yes No Date Sent: